

## High Powered PEMF Semi Kit Parts List

Completely populated motherboard/PCB

100 Watt 100 ohm heat sink resistor

1500 ufd Electrolytic 250 Volt capacitor

Two 6 position rotary switches with 1K resistors mounted

Two rotary switch knobs

110 AC to 12 volt power supply with labeled pigtails

15 amp lighted on/off switch

12 volt cooling fan with grill

Push button pigtail software controlled function switch

Pigtail status with mounted current limit resistor LED

Case mounted fuse holder and 8 amp slow blow fuse.

6 foot power cord

Blank 6 x 5 x 3 Project Box

2 grommets (Used for power cord input & output)

2 Resistor Standoffs

4 nylon PCB standoff washers

10 mounting screws and nuts 4/40

2 tie wraps